Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Repair and painting for toilets at J.P.Park in Ward No.17
2	Administration Approval & Date	JC/RRN/AS/2846/2013-14 Dtd.13-02-2014 by JC RRNZ
3	Technical Sanction Estimate No.& Date	CE/RRN/TS/598/13-14 dtd: 22-02-2014 by CE (RRN)
4	Estimate Amount	Rs.25.00 Lakhs + KRIDL Charges
5	Job Code No.	017-14-000108
6	P-Code	P -0190
7	Agreement No & date	EE/RRN/Proj/AG No./113/2013-14 Dtd.24-02-2014
8	Work order Number & Date	EE/Proj/RRN/W.O/113/2013-14 Dtd.24-02-2014
9	Contract Amount as per Agreement	Rs. 2500000.00/- + KRIDL Charges
10	Bill Amount	Rs.24,99169/- including KRIDL Charges
11	B.R. No. & Date	105/2014-15 dt.30-05-2014
12	Agency	KRIDL
13	M.B. Number & Page No. of Measurement recordes	1443/14-15 Pages 144259 to 144279
14	Date of Inspection	31-8-2015
15	Enclusures	1) Extract of MB No.1443 Page No.144279 2) 4 Number of photos taken during inspection
16	Inspection Report	The above site has been Inspected by me along with the Concerned person. The measurement of the Items which are susceptible to the measurement have been Checked by me and found to be satisfactory

EE (P) RR Nagara

31/8/2015

(R.Sathyanarayana)
Inspection Report officer,